



FIGURE II-29. Tank 16 Primary Wall by Periscope, 1972. Enlarged Salt Deposits and Additional Leak Sites Compared to 1962 Photograph. Chalked numbers are about 4 in. tall.